



Oil Pump 7.04193.02.0

WARRANTY CLAIM: 200128383





PROBLEM DESCRIPTION:

Oil pump (7.04193.02.0) returned from the customer.

Reason of the claim: Leaking lip seal.

Vehicle manufacturer: Peugeot Ripper

Registration date: 2009

Reference: Claim: 200128383

Oil pump serial number: 0035113G17A

Manufacturing date: 13/07/2017








ANALYSIS:

VISUAL CHECK:

The pump on the external surfaces doesn't show any damage.

The rotation present sticking. Opening the pump we found some damage on the housing.

See picture attached:











CONCLUSION:

The wear and the damage present in the housing were caused by the direct contact between it and the rotor without any oil presence.

The reason of the damage is due to lack of oil in priming phase.



OUR HEART BEATS FOR YOUR ENGINE.



Disclaimer

The contents of this document shall be considered confidential information, and it may not be published, reproduced, copied or provided to any person who has an interest in discovering it.

KSPG AG (Rheinmetall Automotive) guarantees not the accuracy or totality of the information provided in the document, nor in any other document or information provided at any time. While this information has been prepared in good faith, no representation or warranty, express or implied, is or will be made and no responsibility or liability is or will be accepted

© Rheinmetall AG I 30/11/2017 6